Transmission Line Rebuild Project


TRANSMISSION LINE TO BE REBUILT

ROUTE ADJUSTMENTS

▲ EXISTING SUBSTATION

1 PHOTO VIEWPOINT LOCATION





Transmission Line Rebuild Project

Photo Viewpoint 1 · Galvanized Steel




1 PHOTO VIEWPOINT LOCATION

DATE: 4/26/2023

TIME: 9:10 AM

DIRECTION: SOUTHWEST









Transmission Line Rebuild Project

Photo Viewpoint 1 · Wood


TRANSMISSION LINE TO BE REBUILT

1 PHOTO VIEWPOINT LOCATION

DATE: 4/26/2023

TIME: 9:10 AM

DIRECTION: SOUTHWEST









Transmission Line Rebuild Project

Photo Viewpoint 2 · Wood


TRANSMISSION LINE TO BE REBUILT

2 PHOTO VIEWPOINT LOCATION

DATE: 4/26/2023

TIME: 11:09 AM

DIRECTION: EAST









Transmission Line Rebuild Project

Photo Viewpoint 3 · Wood


TRANSMISSION LINE TO BE REBUILT

3 PHOTO VIEWPOINT LOCATION

DATE: 4/26/2023


TIME: 11:19 AM

DIRECTION: EAST









Transmission Line Rebuild Project

Photo Viewpoint 4 · Wood


TRANSMISSION LINE TO BE REBUILT

4 PHOTO VIEWPOINT LOCATION


DATE: 4/26/2023


TIME: 11:30 AM

DIRECTION: WEST









Transmission Line Rebuild Project

Photo Viewpoint 5 · Wood


TRANSMISSION LINE TO BE REBUILT

5 PHOTO VIEWPOINT LOCATION

DATE: 4/26/2023

TIME: 11:39 AM

DIRECTION: EAST







Transmission Line Rebuild Project

TREE CLEARING - EXAMPLE AREA

TRANSMISSION LINE TO BE REBUILT RIGHT-OF-WAY/TREE CLEARING ZONE (40 FEET)



